

DO' s

- Always take full PPE (hard hat, high visibility vest, safety shoes, goggles, gloves) when you go to site.
- Be on time and on the first day allow 15 minutes in advance to ensure you are not late for the induction.
- Do sign in and out. This is very important for attendance record and timesheets.
- Make sure the site manager knows where you are.
- Please work safely and responsibly at all times



DO' s

- if you are taking any prescribed medication that may impair your attention or reflexes please inform your supervisor
- Please use welfare facilities provided on site
- At the induction please pay attention for you benefit and that of your fellow workers
- Please carefully read any risk assessments and method statements given to you and ensure you understand them before signing.



Do's & DON'T S
on site



